CLASSIFICATION

CONFIDENTIAL CONFIDENTIAL

50X1-HUM

CENTRAL INTELLIGENCE AGENCY INFORMATION FROM FOREIGN DOCUMENTS OR RADIO BROADCASTS

REPORT

COUNTRY

China

SUBJECT Transportation - Rail

DATE OF

INFORMATION 1950

HOW

Γ

PUBLISHED Daily newspapers

DATE DIST. /O Apr 1950

WHERE

PUBLISHED Hong Kong

NO. OF PAGES 2

DATE

PUBLISHED 16 Feb 1930

LANGUAGE Chinese

SUPPLEMENT TO REPORT NO.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITIDE STATES WITHIN THE REGAME OF THYDOMAGE ACT SO 9. S. C., 21 AND 21, AS AFFENSE TO TRANSPISSION OF THE SYMPLATIC OF THE CONTROL HAVE ASSET OF THE PARTY OF THE PRO-MINISTED BY LAW. REPRODUCTION OF THE PARTY IS PROMISED.

THIS IS UNEVALUATED INFORMATION

SOURCE

Newspapers as indicated.

ATTRIBUTES NUMEROUS RR ACCIDENTS TO CARELESSNESS AND POOR MAINTENANCE

URGES PREVENTION OF ACCIDENTS -- Wen-hui Pao, 16 Feb 50

Pei-p'ing, 14 February -- An editorial, entitled "Stop Carelessness and Improve Techrical Skill; Abolish Accidents and Guarantee Safe Operation of Trains," appeared in a recent issue of the Jen-min T'ieh-tao-pao (People's Railroad News).

The editorial pointed out that although considerable progress was made towards efficient operation of railroads during January and February 1950, nevertheless the number of railroad accidents during the same period had also increased.

The following major accidents have occured so far in 1950:

- 12 January. Collision of trains at Nau-chang-ts'un station in the T'ai-yuan Railroad District. Cause: engineer disregarding stop signal, went through the
- 23 January. Head-on collision of trains at Hua-ch'i-ying station in the Chinnan Railroad District. Cause: erroneous setting of switch. In this accident, the worst since the establishment of the Ministry of Railroads, 62 persons were killed.
- 3 February. Collision of train and handcar, and derailment of train on the section between Li-yuan and Hou-ma in the T'ai-yuan Railroad District.
- 4 February. Collision of trains at Ts'ang-hsien station in the T'ien ching Railroad District. Cause: erroneous setting of switch.
- 7 February. Collision of trains at Lai-yang station in Shen-yang Hsien. Cause: brakeman moved train without proper authority.

CONFIDERIAL

CLASSIFICATION CONFIDENTIAL

STATE NAVY NSRB DISTRIBUTION

ARMY AIR FBI

- 1 -

Sanitized Copy Approved for Release 2011/09/08: CIA-RDP80-00809A000600300042-1



CONFIDENTIAL

50X1-HUM

According to data from all the railroad bureaus in China, railroad accidents, personal injuries, and property loss from the accidents, during the period between 1 January and 5 February 1950, were as follows: train collisions 20, derailments 93, separation of cars 103, minor accidents 157 (including one dynamiting), personal injuries 84 persons, loss of equipment 3 locomotives and 31 other pieces of rolling stock.

FREIGHT TRAIN OVERTURNS ON YUKH-HAN LINE -- Kung-shang Jih-pao, 16 Feb 50

Kuang-chou, 15 February -- Although the Yueh-Han, Che-Kan, and Hsiang-Kuei railroad lines are LDW open to both freight and passenger train traffic, inadequate maintenance and repairs of rails and roadbeds due to lack of parts and materials, are causing numerous accidents. Recently a freight train from Shang-hai overturned at Ying-te station on the Yueh-Han line, and on 13 February, another train was derailed near Wu-ch'ang station.

-END -

- 2 -

CONFIDENTIAL

COMPRESSION